



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Abandonedme	HOMER PWS			System ID Number:	IL0190300	Current Inventory Date:	3/11/2024				
*Please enter totals in the empty box next to each category	Total Service lines:	586	Total Lead:	0	Total Non-Lead:	586	Total Galvanized Requiring replacement:	0	Total Unknown:	0	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:  Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities  Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
100 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
100 E WOLF	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
101 E COFFEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
101 LACEY LANE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
101 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
101 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
101 WOLF	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
102 E FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
102 JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
102 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
102 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
102 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
102 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
102 W MARY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
103 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
103 E WOLF	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
103 KAY DRIVE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	c	c	NL	N	N/R	N			N	
103 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
103 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
103 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
103 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
103 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
103 W. MARY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
104 E FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
104 E WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
104 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	P	C	NL	N	N/R	N			N	
104 N CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
104 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
104 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	

104 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
104 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
104 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N
105 1/2 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	P	P	NL	N	N/R	N			N
105 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
105 KAY DRIVE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N
105 MADISON	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 MAPLE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
105 S CAROLINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N
105 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
105 S JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
105 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
105 W SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
105 W WHITE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	Abandoned	Abandoned	Abandoned	NL	N	N/R	N			N
106 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 E WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
106 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
106 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 S CAROLINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
106 S MAPLE	LA2J022	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
106 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
106 SCHOOLVIEW DR	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
106 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
106 W WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
107 JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N
107 KAY DRIVE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
107 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
107 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
107 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
107 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
107 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 1/2 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
108 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
108 E FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
108 E WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
108 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 S JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
108 S LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N
108 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
108 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 W SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
108 W WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
109 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
109 KAY DRIVE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
109 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
109 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
109 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N

109 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
109 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
109 SCHOOL	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	P	P	NL	N	N/R	N			N	
109 WAVERLY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
11 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 E CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
110 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 N MAIN ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
110 N MAIN ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
110 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 N WHITE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 S CAROLINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 S LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
110 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N	
110 W MARY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
110 WAVERLY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
111 KAY DRIVE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
111 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
111 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
111 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
111 S LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
111 S MAIN ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
111 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
112 1/2 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
112 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
112 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
112 S LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
112 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
112 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
113 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
114 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
114 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
115 SCHOOL VIEW DR B-3 yellow	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	P	P	NL	N	N/R	N			N	
116 LYNN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
116 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
116 S MAIN ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	Abandoned	NL	N	N/R	N			N	
118 S MAIN	LA3R023	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
119 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
12 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
120 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
122 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
123 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	Abandoned	NL	N	N/R	N			N	
123 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
125 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
125 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
130 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
2 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 E COFFEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
201 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 E MONROE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 W FOURTH	LA3S028	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
202 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
202 E FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
202 E MARY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
202 E SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	



207 E THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
207 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
207 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
207 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
207 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
207 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
207 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
207 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 E MONROE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 E SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
208 E THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 N CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
208 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
208 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
208 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
208 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 W SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 W SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
208 W WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
209 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
209 N WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
209 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N	
209 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
209 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
209 W CRITTENDEN	LA3S026	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
210 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
210 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
210 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
210 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
210 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
210 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
210 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
210 WAVERLY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
2763 COUNTY ROAD 1050 N	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
2763 CR 1050N	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
2775 CR 1050 N	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
3 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
300 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
300 W MARY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 E COFFEEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N	
301 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 MILDRED	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S CAROLINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 SANDS DR	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N	
301 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
302 JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
302 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
302 S CAROLINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	



308 W SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
308 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
308 WAVERLY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
309 N WEST ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
309 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
309 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
309 WAVERLY	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 E SOUTH ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
310 JOSEPHINE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 MILDRED	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 N EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 N ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
310 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
310 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
310 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
312 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
313 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
314 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
315 W CRITTENDEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
4 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
401 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
401 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
401 S WEST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
401 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
402 E COFEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
402 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
402 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
402 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
402 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
403 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
403 E SOUTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
403 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
403 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
404 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
404 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
404 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
404 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
405 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
405 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
405 W THIRD	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
406 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
406 S CHURCH ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
406 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
406 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
406 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
406 W FOURTH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
407 E FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
407 E SECOND	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	P	P	NL	N	N/R	N			N
407 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
407 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
407 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	Abandoned	Abandoned	NL	N	N/R	N			N
407 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
407 W FIRST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
407 W SECOND ST.	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
408 S ELLEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
408 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N







705 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
706 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
706 S MAIN	LA35024	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
707 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
707 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
708 1/2 S MAIN ST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
708 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
708 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
709 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
709 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
710 S CHURCH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
710 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
710 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	G	NL	N	N/R	N			N
711 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
711 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
712 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
712 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
713 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
714 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
715 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
716 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
717 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
718 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
719 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
720 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
721 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
722 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
723 S EAST	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
8 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
800 W FIRST	LA35027	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
806 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
808 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
811 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
9 GLENDALE	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
902 S MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
903 S MAIN	LA3R029	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
A SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N
A-1 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
A-2 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
A-3 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
A-4 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
B SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N
B-4 SCHOOLVIEW	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
E COFFEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
E COFFEEN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N
N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	Abandoned	Abandoned	Abandoned	NL	N	N/R	N			N
N MAIN	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION		C	G	NL	N	N/R	N			N
SCHOOLVIEW B-1 blue	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
SCHOOLVIEWAPT B-2	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N
W WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	C	C	P	NL	N	N/R	N			N
W WABASH	N/A	N	N	Unknown	Unknown	VISUAL INSPECTION	Abandoned	Abandoned	Abandoned	NL	N	N/R	N			N